

**Request under the *Freedom of Information and Protection of Privacy Act*:**

*With regard to the Baynes Sound Connector:*

- 1. The dates of all cable exchanges that have taken place, including since the vessel has been in full service as well as training and practice exchanges prior to full service;*
- 2. Serial numbers and asset numbers of the cables removed and installed, as well as the location (south guide, drive, north guide) of the changed cables;*
- 3. A list of spools of cables that BC Ferries has in its possession, including serial numbers and asset numbers.*

**Response:**

## History Notes:

April 27, 2015	Cables placed in water – Initial Lay of Cables
November 18, 2015	Drive Cable Change-out – Procedural Training
December 9, 2015	North guide cable change-out – Procedural Training
January 12, 2016	South guide cable change-out – Procedural Training
January 26, 2016	Drive cable change-out – Procedural Training
November 17, 2016	Drive cable change-out – Service Cycle
November 30, 2016	South guide cable change-out – Service Cycle
November 2016	Manufacturer Date of Spare Cable Serial Number WRI – 131598-01 Asset Number: 44951

Cable System Serial Number Chart

<b>Cable System Layout as of April 27, 2015 (Cable Install)</b>			
<b>Location</b>	<b>Manufacturer S/N</b>	<b>BCF Asset No</b>	<b>Install Date</b>
North Guide Cable	WRI, 130172-03	41874	2015-04-27
Drive Cable	WRI, 130172-04	41878	2015-04-27
South Guide Cable	WRI, 130172-01	41876	2015-04-27
Spare Cable	WRI, 130172-02	42076	

<b>Cable System Layout as of November 18, 2015 (Drive Cable Change-out)</b>			
<b>Location</b>	<b>Manufacturer S/N</b>	<b>BCF Asset No</b>	<b>Install Date</b>
North Guide Cable	WRI, 130172-03	41874	2015-04-27
Drive Cable	WRI, 130172-02	42076	2015-11-18
South Guide Cable	WRI, 130172-01	41876	2015-04-27
Spare Cable	WRI, 130172-04	41878	

<b>Cable System Layout as of December 09, 2015 (North Guide Cable Change-out)</b>			
<b>Location</b>	<b>Manufacturer S/N</b>	<b>BCF Asset No</b>	<b>Install Date</b>
North Guide Cable	WRI, 130172-04	41878	2015-12-09
Drive Cable	WRI, 130172-02	42076	2015-11-18
South Guide Cable	WRI, 130172-01	41876	2015-04-27
Spare Cable	WRI, 130172-03	41874	

<b>Cable System Layout as of January 12, 2016 (South Guide Cable Change-out)</b>			
<b>Location</b>	<b>Manufacturer S/N</b>	<b>BCF Asset No</b>	<b>Install Date</b>
North Guide Cable	WRI, 130172-04	41878	2015-12-09
Drive Cable	WRI, 130172-02	42076	2015-11-18
South Guide Cable	WRI, 130172-03	41874	2016-01-12
Spare Cable	WRI, 130172-01	41876	

<b>Cable System Layout as of January 26, 2016 (Drive Cable Change-out)</b>			
<b>Location</b>	<b>Manufacturer S/N</b>	<b>BCF Asset No</b>	<b>Install Date</b>
North Guide Cable	WRI, 130172-04	41878	2015-12-09
Drive Cable	WRI, 130172-01	41876	2016-01-26
South Guide Cable	WRI, 130172-03	41874	2016-01-12
Spare Cable	WRI, 130172-02	42076	

<b>Cable System Layout: November 17, 2016 (Drive Cable change-out)</b>			
<b>Location</b>	<b>Manufacturer S/N</b>	<b>BCF Asset No</b>	<b>Install Date</b>
North Guide Cable	WRI, 130172-04	41878	2015-12-09
Drive Cable	WRI, 130172-02	42076	2016-11-17
South Guide Cable	WRI, 130172-03	41874	2016-01-12
Spare Cable	WRI, 130172-01	41876	

<b>Cable System Layout: November 30, 2016 (South Guide Cable change-out)</b>			
<b>Location</b>	<b>Manufacturer S/N</b>	<b>BCF Asset No</b>	<b>Install Date</b>
North Guide Cable	WRI, 130172-04	41878	2015-12-09
Drive Cable	WRI, 130172-02	42076	2016-11-17
South Guide Cable	WRI, 130172-01	41876	2016-11-30
Spare Cable	WRI, 130172-03	41874	

<b>Cable System Layout: November 21, 2016 (Received New Spare Cable)</b>			
<b>Location</b>	<b>Manufacturer S/N</b>	<b>BCF Asset No</b>	<b>Install Date</b>
North Guide Cable	WRI, 130172-04	41878	2015-12-09
Drive Cable	WRI, 130172-02	42076	2016-11-17
South Guide Cable	WRI, 130172-01	41876	2016-11-30
Existing Spare Cable (Prep for Disposal)	WRI, 130172-03	41874	
New Spare Cable	WRI, 131598-01	44951	