



s. 22 - signature



Work Order: CENT.1232744



Status Code: WSCH
 Priority: 8
 GL Account: 540.210.1071.?????.00.00000.0000.10
 Ownergroup/ Plan Area: TM-LR

Reported by: CACOPLAN
 Date: 04-Mar-2016
 Phone #:
 Project #: s. 22 - employee phone number

Reference: Parent:
 Location: BSC-2210 Gearing, Reduction and Reversing

Asset:

Craft: MCA Site/Vessel: BSC Worktype: PM/INSP
 Shift: PM: BSC-2210-PM-40

Target Start: 07-Mar-2016 Target Finish: 10-Mar-2016

Work Requested: Weekly Inspection of Drive & Guide Cables - March 10/16
 Includes three vessel cables

Job Plan: 2210-BSC-SJ-40
 Job Plan Desc: Cable Inspection
 Supervisor: BNELSON

Meter Reading:
 Last Reading Date:

Planned Labour:

Task	Craft	Quantity	Hours
10	MCA	1	1

Operations:

Task	Description
10	Inspect Drive & Guide Cables Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables. Visual damage includes; Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands

Report any of the above to supervisor.

Completion Remarks:



Work Order: CENT.1232744

Problem: _____
Cause: _____
Remedy: _____
Downtime: _____
Remarks: _____

03/04/2016
Completed By

Alex. K... ..
Completed By

Completed Date



Work Order: CENT.1234699

s. 22 - signature



Status Code: WSCH
Priority: 8
GL Account: 540.210.1071.?????.00.00000.0000.10
Ownergroup/ Plan Area: TM-LR

Reported by: CACOPLAN
Date: 14-Mar-2016

Phone #:
Project #: s. 22 - employee phone number

Reference: Parent:
Location: BSC-2210 Gearing, Reduction and Reversing

Asset:

Craft: MCA Site/Vessel: BSC Worktype: PM/INSP
Shift: PM: BSC-2210-PM-40

Target Start: 17-Mar-2016 Target Finish: 17-Mar-2016

Work Requested: Weekly Inspection of Drive & Guide Cables - March 17/16
Includes all three vessel cables

Job Plan: 2210-BSC-SJ-40

Job Plan Desc: Cable Inspection Meter Reading:
Supervisor: BNELSON Last Reading Date:

Planned Labour:

Task	Craft	Quantity	Hours
10	MCA	1	1

Operations:

Task	Description
10	<p>Inspect Drive & Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables. Visual damage includes; Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p>

Report any of the above to supervisor.

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK



Work Order: CENT.1234699

Completion Remarks:

Problem:

Cause:

Remedy:

Downtime:

Remarks:

Load Cell Readings at Denman West while the BSC is in the dock on Denman Island. North Cable 30,900 Drive Cable 102,900 South Cable 25,150.

Cables visually inspected at a reduced speed with the assistance of the deck crew. All 3 cables are showing wear. The drive cable showing the more wear than the North & South cables. No change in color, deformity; no propeller nicks or loose cable strands observed.

Completed By

Completed By

Completed Date

S. Bagwell

March, 19, 2016



Work Order: CENT.1234701



Status Code: COMP **Reported by:** CACOPLAN
Priority: 8 **Date:** 14-Mar-2016
GL Account: 540.210.1071.?????.00.00000.0000.10 **Phone #:**
Ownergroup/ Plan Area: TM-LR **Project #:** s. 22 - employee phone number
Reference: **Parent:**
Location: BSC-2210 Gearing, Reduction and Reversing
Asset:
Craft: MCA **Site/Vessel:** BSC **Worktype:** PM/INSP
Shift: **PM:** BSC-2210-PM-40
Target Start: 24-Mar-2016 **Target Finish:** 24-Mar-2016
Work Requested: Weekly Inspection of Drive & Guide Cables - March 24/16
Includes all three vessel cables
Job Plan: 2210-BSC-SJ-40
Job Plan Desc: Cable Inspection **Meter Reading:**
Supervisor: BNELSON **Last Reading Date:**

Planned Labour:

Task	Craft	Quantity	Hours
10	MCA	1	1

Operations:

Task	Description
10	Inspect Drive & Guide Cables Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables. Visual damage Includes; Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands

Report any of the above to supervisor.

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK



Work Order: CENT.1234701

Completion Remarks:

04-Apr-2016

comp

NOTES:

Problem: NO MAJOR DEFORMITIES FOUND, NOTHING OF
Cause: CONCERN.
Remedy: _____
Downtime: _____
Remarks: _____

JAMES PHILLIPS

Completed By

Completed By

MAR 24 / 16

Completed Date



s. 22 - signature



Work Order: CENT.1239467



Status Code: WSCH **Reported by:** CACOPLAN
Priority: 8 **Date:** 04-Apr-2016
GL Account: 540.210.1071.?????.00.00000.0000.10 **Phone #:**
Ownergroup/ Plan Area: TM-LR **Project #:** s. 22 - employee phone number
Reference: **Parent:**
Location: BSC-2210 **Gearing, Reduction and Reversing**
Asset:
Craft: MCA **Site/Vessel:** BSC **Worktype:** PM/INSP
Shift: **PM:** BSC-2210-PM-40
Target Start: 04-Apr-2016 **Target Finish:** 04-Apr-2016
Work Requested: Weekly Inspection of Drive & Guide Cables - April 4/16
 Includes all three vessel cables
Job Plan: 2210-BSC-SJ-40
Job Plan Desc: Cable Inspection **Meter Reading:**
Supervisor: BNELSON **Last Reading Date:**

Planned Labour:

Task	Craft	Quantity	Hours
10	MCA	1	1

Operations:

Task	Description																
10	<ul style="list-style-type: none"> ✓ Inspect Drive & Guide Cables ✓ Visual inspection of the cables whilst vessel is in transit. ✓ Report any visual damage that may be seen on the cables. ✓ Visual damage includes; <table style="margin-left: 20px; border: none;"> <tr> <td>Change in color (cables are blue)</td> <td>N</td> <td>Cable Tension</td> <td>S</td> </tr> <tr> <td>Deformity</td> <td></td> <td>D</td> <td></td> </tr> <tr> <td>Propeller nicks.</td> <td>30,750</td> <td>35,500</td> <td>25,200</td> </tr> <tr> <td>Loose cable strands</td> <td></td> <td></td> <td></td> </tr> </table> 	Change in color (cables are blue)	N	Cable Tension	S	Deformity		D		Propeller nicks.	30,750	35,500	25,200	Loose cable strands			
Change in color (cables are blue)	N	Cable Tension	S														
Deformity		D															
Propeller nicks.	30,750	35,500	25,200														
Loose cable strands																	

Report any of the above to supervisor.

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK



Work Order: CENT.1239467

Completion Remarks:

Problem:

Cause:

Remedy:

Downtime:

Remarks:

Drive cable showing more wear than guide cables.

S. Bagwell

Completed By

D. Pickford

Completed By

March 11/16

Completed Date



s. 22 - signature



Work Order: CENT.1239724



Status Code: WSCH
 Priority: 8
 GL Account: 540.210.1071.?????.00.00000.0000.10
 Ownergroup/ Plan Area: TM-LR

Reported by: CACOPLAN
 Date: 05-Apr-2016
 Phone #:
 Project #: s. 22 - employee phone number

Reference: Parent:
 Location: BSC-2210 Gearing, Reduction and Reversing

Asset:
 Craft: MCA Site/Vessel: BSC Worktype: PM/INSP
 Shift: PM: BSC-2210-PM-40

Target Start: 18-Apr-2016 Target Finish: 18-Apr-2016

Work Requested: Weekly Inspection of Drive & Guide Cables - April 18/16
 Includes all three vessel cables

Job Plan: 2210-BSC-SJ-40
 Job Plan Desc: Cable Inspection Meter Reading:
 Supervisor: BNELSON Last Reading Date:

Planned Labour:

Task	Craft	Quantity	Hours
10	MCA	1	1

Operations:

Task	Description			
10	Inspect Drive & Guide Cables Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables. Visual damage includes; Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands	N	D	S
		30400	35000	26750

Report any of the above to supervisor.

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK



Work Order: CENT.1239724

Completion Remarks:

Problem: _____
Cause: _____
Remedy: _____
Downtime: _____
Remarks: Visible wear - no damage

S. Bagwell
Completed By

Completed By

March 6 / 2016
Completed Date



s. 22 - signature



Work Order: CENT.1242177



Status Code: COMP **Reported by:** CACOPLAN
Priority: 8 **Date:** 19-Apr-2016
GL Account: 540.210.1071.?????.00.00000.0000.10 **Phone #:**
Ownergroup/ Plan Area: TM-LR **Project #:** s. 22 - employee phone number
Reference: **Parent:**
Location: BSC-2210 Gearing, Reduction and Reversing
Asset:
Craft: MCA **Site/Vessel:** BSC **Worktype:** PM/INSP
Shift: **PM:** BSC-2210-PM-40
Target Start: 25-Apr-2016 **Target Finish:** 25-Apr-2016
Work Requested: Weekly Inspection of Drive & Guide Cables - April 25/16
 Includes all three vessel cables
Job Plan: 2210-BSC-SJ-40
Job Plan Desc: Cable Inspection **Meter Reading:**
Supervisor: BNELSON **Last Reading Date:**

Planned Labour:

Task	Craft	Quantity	Hours
10	MCA	1	1

Operations:

Task	Description
10	Inspect Drive & Guide Cables Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables. Visual damage includes; Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands

Report any of the above to supervisor.

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK



Work Order: CENT.1242177

Completion Remarks:

25-Apr-2016

comp

Problem: inspect cables
Cause: _____
Remedy: _____
Downtime: _____
Remarks: _____

s. 22 - signature



Completed By

May 18. 16

Completed By

Completed Date