



Work Order: CENT.1252655



**Status Code:** COMP **Reported by:** CACOPLAN  
**Priority:** 8 **Date:** 06-Jun-2016  
**GL Account:** 540.210.1071.77777.00.00000.0000.10 **Phone #:**   
**Ownergroup/ Plan Area:** TM-LR **Project #:** s. 22 - employee phone number  
**Reference:** **Parent:**  
**Location:** BSC-2210 **Gearing, Reduction and Reversing**  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 16-Jun-2016 **Target Finish:** 16-Jun-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - June 16/16  
Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** BNELSON **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1252655

**Operations:**

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

---

**Completion Remarks:** 22-Jun-2016

comp

BSC in berth at DENW

date - June 17/16  
time - 08:30

north cable - 30,000  
drive cable - 12,000  
south cable - 16,000

cables show no signs of serious damage. no kinks, bnds, thinning, visible broken wires or parting of cables  
some surface loss of plastic coating is visible on all 3 cables and more pronounced on the drive cable  
no large pieces or deep pieces are missing  
cables have some surface rust discoloration in areas but no signs of pitted rust or internal rust  
cable tension displayed for the south cable & drive cable @ DENW is low  
cables may need to be re-tensioned

spelter sockets at DENW inspect & appear in good shape

---



Work Order: CENT.1252657



**Status Code:** COMP **Reported by:** CACOPLAN  
**Priority:** 8 **Date:** 06-Jun-2016  
**GL Account:** 540.210.1071.7777.00.00000.0000.10 **Phone #:**   
**Ownergroup/ Plan Area:** TM-LR **Project #:** s. 22 - employee phone number  
**Reference:** **Parent:**  
**Location:** BSC-2210 Gearing, Reduction and Reversing  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 23-Jun-2016 **Target Finish:** 23-Jun-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - June 23/16  
Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** BNELSON **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1252657

Operations:

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

**Completion Remarks:** 22-Jun-2016

comp

date - June 21/16

time - 11:30

north cable - 29550

drive cable - 12150

south cable - 25000

no defects found

no issues at this time

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

\_\_\_\_\_  
**Completed By**                      **Completed By**                      **Completed Date**



Work Order: CENT.1257805



**Status Code:** COMP  
**Priority:** 8  
**GL Account:** 540.210.1071.?????.00.00000.0000.10  
**Ownergroup/ Plan Area:** TM-LR  
**Reference:**

**Reported by:** CACOPLAN  
**Date:** 04-Jul-2016  
**Phone #:**   
**Project #:**

s. 22 - employee phone number

**Location:** BSC-2210      Gearing, Reduction and Reversing  
**Asset:**

**Craft:** MCA      **Site/Vessel:** BSC      **Worktype:** PM/INSP  
**Shift:**      **PM:** BSC-2210-PM-40

**Target Start:** 04-Jul-2016      **Target Finish:** 04-Jul-2016

**Work Requested:** Weekly Inspection of Drive & Guide Cables - July 4/16  
 Includes all three vessel cables

**Job Plan:** 2210-BSC-SJ-40

**Job Plan Desc:** Cable Inspection

**Supervisor:** BNELSON

**Meter Reading:**

**Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1257805

Operations:

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

Completion Remarks:

12-Jul-2016

comp  
 July 8/16 @ 08:00  
 north - 31250  
 drive - 27250  
 south - 25680

no issues found  
 no obvious deformities

Problem: \_\_\_\_\_  
 Cause: \_\_\_\_\_  
 Remedy: \_\_\_\_\_  
 Downtime: \_\_\_\_\_  
 Remarks: \_\_\_\_\_

Completed By

Completed By

Completed Date



Work Order: CENT.1257807



**Status Code:** COMP  
**Priority:** 8  
**GL Account:** 540.210.1071.77777.00.00000.0000.10  
**Ownergroup/ Plan Area:** TM-LR  
**Reference:**

**Reported by:** CACOPLAN  
**Date:** 04-Jul-2016  
**Phone #:**   
**Project #:**

s. 22 - employee phone number

**Location:** BSC-2210      Gearing, Reduction and Reversing  
**Asset:**

**Craft:** MCA      **Site/Vessel:** BSC      **Worktype:** PM/INSP  
**Shift:**      **PM:** BSC-2210-PM-40

**Target Start:** 11-Jul-2016      **Target Finish:** 11-Jul-2016

**Work Requested:** Weekly Inspection of Drive & Gulde Cables - July 11/16  
 Includes all three vessel cables

**Job Plan:** 2210-BSC-SI-40  
**Job Plan Desc:** Cable Inspection  
**Supervisor:** BNELSON

**Meter Reading:**  
**Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3,00



Work Order: CENT.1257807

**Operations:**

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

**Completion Remarks:** 03-Aug-2016  
 Comp

Problem: \_\_\_\_\_  
 Cause: \_\_\_\_\_  
 Remedy: \_\_\_\_\_  
 Downtime: \_\_\_\_\_  
 Remarks: \_\_\_\_\_

\_\_\_\_\_  
**Completed By**                      **Completed By**                      **Completed Date**





Work Order: CENT.1257809



Status Code: COMP  
Priority: 8  
GL Account: 540.210.1071.?????.00.00000.0000.10  
Ownergroup/ Plan Area: TM-LR

Reported by: CACOPLAN  
Date: 04-Jul-2016  
Phone #:   
Project #:

s. 22 - employee phone number

Reference:  
Location: BSC-2210      Gearing, Reduction and Reversing  
Asset:

Craft: MCA      Site/Vessel: BSC      Worktype: PM/INSP  
Shift:      PM: BSC-2210-PM-40

Target Start: 18-Jul-2016      Target Finish: 18-Jul-2016

Work Requested: Weekly Inspection of Drive & Guide Cables - July 18/16  
Includes all three vessel cables

Job Plan: 2210-BSC-SJ-40  
Job Plan Desc: Cable Inspection  
Supervisor: BNELSON

Meter Reading:  
Last Reading Date:

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1257809

**Operations:**

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks, Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

**Completion Remarks:** 21-Jul-2016

Comp  
 July 21/16 @ 08:00  
 north - 30200  
 drive - 33650  
 south - 24400

no issues found  
 no obvious deformities

**Problem:** \_\_\_\_\_

**Cause:** \_\_\_\_\_

**Remedy:** \_\_\_\_\_

**Downtime:** \_\_\_\_\_

**Remarks:** \_\_\_\_\_

\_\_\_\_\_  
**Completed By**

\_\_\_\_\_  
**Completed By**

\_\_\_\_\_  
**Completed Date**



Work Order: CENT.1257811



Status Code: COMP  
Priority: 8  
GL Account: 540.210.1071.?????.00.00000.0000.10  
Ownergroup/ Plan Area: TM-LR

Reported by: CACOPLAN  
Date: 04-Jul-2016  
Phone #:   
Project #:

s. 22 - employee phone number

Reference: Parent:  
Location: BSC-2210 Gearing, Reduction and Reversing  
Asset:

Craft: MCA Site/Vessel: BSC Worktype: PM/INSP  
Shift: PM: BSC-2210-PM-40

Target Start: 25-Jul-2016 Target Finish: 25-Jul-2016

Work Requested: Weekly Inspection of Drive & Guide Cables - July 25/16  
Includes all three vessel cables

Job Plan: 2210-BSC-SJ-40

Job Plan Desc: Cable Inspection

Supervisor: BNELSON

Meter Reading:  
Last Reading Date:

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1257811

Operations:

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

Completion Remarks:

02-Aug-2016

Comp  
July 29th, 2016

Time: 11:00  
North cable 30500  
Drive cable 30500  
South cable 24500

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

Completed By

Completed By

Completed Date



Work Order: CENT.1257813



**Status Code:** COMP  
**Priority:** 8  
**GL Account:** 540,210,1071.?????.00.00000.0000.10  
**Ownergroup/ Plan Area:** TM-LR  
**Reference:**  
**Location:** BSC-2210      Gearing, Reduction and Reversing  
**Asset:**  
**Craft:** MCA      **Site/Vessel:** BSC      **Worktype:** PM/INSP  
**Shift:**      **PM:** BSC-2210-PM-40  
**Target Start:** 01-Aug-2016      **Target Finish:** 01-Aug-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Aug 1/16  
 Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection      **Meter Reading:**  
**Supervisor:** BNELSON      **Last Reading Date:**

**Reported by:** CACOPLAN  
**Date:** 04-Jul-2016  
**Phone #:**   
**Project #:** s. 22 - employee phone number  
**Parent:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1257813

Operations:

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

Completion Remarks:

09-Aug-2016

Comp  
No defects or issues found.

August 6, 2016  
Time - 11:00 am

North cable - 31274  
Drive cable - 30576  
South cable - 27631

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

Completed By

Completed By

Completed Date



Work Order: CENT.1257815



Status Code: COMP  
Priority: 8  
GL Account: 540.210.1071.?????.00.00000.0000.10  
Ownergroup/ Plan Area: TM-LR

Reported by: CACOPLAN  
Date: 04-Jul-2016  
Phone #:   
Project #:

s. 22 - employee phone number

Reference: Parent:  
Location: BSC-2210 Gearing, Reduction and Reversing  
Asset:

Craft: MCA Site/Vessel: BSC Worktype: PM/INSP  
Shift: PM: BSC-2210-PM-40

Target Start: 08-Aug-2016 Target Finish: 08-Aug-2016

Work Requested: Weekly Inspection of Drive & Guide Cables - Aug 8/16  
Includes all three vessel cables

Job Plan: 2210-BSC-SJ-40

Job Plan Desc: Cable Inspection

Supervisor: BNELSON

Meter Reading:

Last Reading Date:

Planned Labour:

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1257815

Operations:

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - Include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

Completion Remarks:

01-Sep-2016

comp  
labour charged to "start up" WO

date - Aug 8/16  
time - 07:00  
north cable - 29500  
drive cable - 27400  
south cable - 25600

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

Completed By

Completed By

Completed Date





Work Order: CENT.1257817



Status Code: COMP  
Priority: 8  
GL Account: 540.210.1071.?????.00.00000.0000.10  
Ownergroup/ Plan Area: TM-LR  
Reference:

Reported by: CACOPLAN  
Date: 04-Jul-2016  
Phone #:   
Project #: s. 22 - employee phone number

Location: BSC-2210 Gearing, Reduction and Reversing  
Asset:

Craft: MCA Site/Vessel: BSC Worktype: PM/INSP  
Shift: PM: BSC-2210-PM-40

Target Start: 15-Aug-2016 Target Finish: 15-Aug-2016

Work Requested: Weekly Inspection of Drive & Guide Cables - Aug 15/16  
Includes all three vessel cables

Job Plan: 2210-BSC-SJ-40

Job Plan Desc: Cable Inspection

Supervisor: BNELSON

Meter Reading:  
Last Reading Date:

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1257817

**Operations:**

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - Include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

**Completion Remarks:**

18-Aug-2016

comp  
date - Aug 15/16  
time - 09:00  
north cable - 31600  
drive cable - 31210  
south cable - 24100

**Problem:** \_\_\_\_\_  
**Cause:** \_\_\_\_\_  
**Remedy:** \_\_\_\_\_  
**Downtime:** \_\_\_\_\_  
**Remarks:** \_\_\_\_\_

Completed By	Completed By	Completed Date
--------------	--------------	----------------



Work Order: CENT.1257819



Status Code: COMP  
Priority: 8  
GL Account: 540.210.1071.?????.00.00000.0000.10  
Ownergroup/ Plan Area: TM-LR  
Reference:

Reported by: CACOPLAN  
Date: 04-Jul-2016  
Phone #:   
Project #:

s. 22 - employee phone number

Location: BSC-2210      Gearing, Reduction and Reversing  
Asset:

Parent:

Craft: MCA      Site/Vessel: BSC      Worktype: PM/INSP  
Shift:      PM: BSC-2210-PM-40

Target Start: 22-Aug-2016      Target Finish: 22-Aug-2016

Work Requested: Weekly Inspection of Drive & Guide Cables - Aug 22/16  
Includes all three vessel cables

Job Plan: 2210-BSC-SJ-40  
Job Plan Desc: Cable Inspection  
Supervisor: BNELSON

Meter Reading:  
Last Reading Date:

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1257819

Operations:

Task	Description
------	-------------

10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - Include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p>
----	--

Report any of the above to trades supervisor.

note tension readings of cables including date & time

date \_\_\_\_\_

time \_\_\_\_\_

North Cable \_\_\_\_\_

Drive Cable \_\_\_\_\_

South Cable \_\_\_\_\_

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK

Completion Remarks:

25-Aug-2016

comp

date - Aug 24/16

time - 07:30

north cable - 29750

drive cable - 28550

south cable - 23850

no issues found

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

Completed By

Completed By

Completed Date



Work Order: CENT.1257821



**Status Code:** COMP  
**Priority:** 8  
**GL Account:** 540.210.1071.?????.00.00000.0000.10  
**Ownergroup/  
Plan Area:** TM-LR  
**Reference:**

**Reported by:** CACOPLAN  
**Date:** 04-Jul-2016  
**Phone #:**   
**Project #:** s. 22 - employee phone number

**Location:** BSC-2210      Gearing, Reduction and Reversing  
**Asset:**

**Craft:** MCA      **Site/Vessel:** BSC      **Worktype:** PM/INSP  
**Shift:**      **PM:** BSC-2210-PM-40

**Target Start:** 29-Aug-2016      **Target Finish:** 29-Aug-2016

**Work Requested:** Weekly Inspection of Drive & Guide Cables - Aug 29/16  
 Includes all three vessel cables

**Job Plan:** 2210-BSC-SJ-40

**Job Plan Desc:** Cable Inspection

**Supervisor:** BNELSON

**Meter Reading:**  
**Last Reading Date:**

---

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00

---



Work Order: CENT.1257821

**Operations:**

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - Include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

**Completion Remarks:**

01-Sep-2016

comp  
date - Aug 29/16  
time - 07:30  
north cable - 29500  
drive cable - 27600  
south cable - 25800

**Problem:** \_\_\_\_\_  
**Cause:** \_\_\_\_\_  
**Remedy:** \_\_\_\_\_  
**Downtime:** \_\_\_\_\_  
**Remarks:** \_\_\_\_\_

Completed By

Completed By

Completed Date



Work Order: CENT.1264703



**Status Code:** COMP **Reported by:** AUTOGEN  
**Priority:** 8 **Date:** 08-Aug-2016  
**GL Account:** 540.210.1071.?????.00.00000.0000.10 **Phone #:**  
**Ownergroup/ Plan Area:** TM-LR **Project #:**  
**Reference:** **Parent:**  
**Location:** BSC-2210 Gearing, Reduction and Reversing  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 05-Sep-2016 **Target Finish:** 08-Sep-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Sept 8/16  
 Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** BNELSON **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1264703

**Operations:**

Task	Description
------	-------------

10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p>
----	--

Report any of the above to trades supervisor.

note tension readings of cables including date & time

date \_\_\_\_\_

time \_\_\_\_\_

North Cable \_\_\_\_\_

Drive Cable \_\_\_\_\_

South Cable \_\_\_\_\_

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK

**Completion Remarks:**

22-Nov-2016

comp

Date: Sept. 6, 2016

Time: 0900

North cable: 29,500

Drive cable: 31,800

South cable: 25,750

No issues found.

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

\_\_\_\_\_  
**Completed By**

\_\_\_\_\_  
**Completed By**

\_\_\_\_\_  
**Completed Date**





Work Order: CENT.1265397



**Status Code:** COMP **Reported by:** AUTOGEN  
**Priority:** 8 **Date:** 13-Aug-2016  
**GL Account:** 540.210.1071.?????.00.00000.0000.10 **Phone #:**  
**Ownergroup/ Plan Area:** TM-LR **Project #:**  
**Reference:** **Parent:**  
**Location:** BSC-2210 **Gearing, Reduction and Reversing**  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 12-Sep-2016 **Target Finish:** 12-Sep-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Sept 15/16  
Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** BNELSON **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1265397

**Operations:**

Task	Description
10	<p><b>Inspect Drive &amp; Guide Cables</b></p> <p>Visual Inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

**Completion Remarks:**

19-Sep-2016

comp  
All cables in good shape.

Date: Sept 18, 2016  
Time: 0900  
North cable: 29,700  
Drive cable: 25,900  
South cable: 24,900

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

\_\_\_\_\_  
**Completed By**

\_\_\_\_\_  
**Completed By**

\_\_\_\_\_  
**Completed Date**



Work Order: CENT.1268779



**Status Code:** COMP **Reported by:** AUTOGEN  
**Priority:** 8 **Date:** 08-Sep-2016  
**GL Account:** 540.210.1071.?????.00.00000.0000.10 **Phone #:**  
**Ownergroup/ Plan Area:** TM-LR **Project #:**  
**Reference:** **Parent:**  
**Location:** BSC-2210 Gearing, Reduction and Reversing  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 22-Sep-2016 **Target Finish:** 22-Sep-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Sept 22/16  
 Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** BNELSON **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1268779

Operations:

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

Completion Remarks: 27-Sep-2016

comp  
Date: Sept. 26/16  
Time: 0800  
North cable: 29500  
Drive cable: 29100  
South cable: 24400

Problem: \_\_\_\_\_  
Cause: \_\_\_\_\_  
Remedy: \_\_\_\_\_  
Downtime: \_\_\_\_\_  
Remarks: \_\_\_\_\_

Completed By

Completed By

Completed Date



Work Order: CENT.1270316



**Status Code:** COMP **Reported by:** AUTOGEN  
**Priority:** 8 **Date:** 15-Sep-2016  
**GL Account:** 540.210.1071.7777.00.00000.0000.10 **Phone #:**  
**Ownergroup/ Plan Area:** TM-LR **Project #:**  
**Reference:** **Parent:**  
**Location:** BSC-2210 Gearing, Reduction and Reversing  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 29-Sep-2016 **Target Finish:** 29-Sep-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Sept 29/16  
Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** BNELSON **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3,00



Work Order: CENT.1270316

Operations:

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

Completion Remarks: 13-Oct-2016

comp  
 Date: October 1st, 2016  
 Time: 0745  
 North Cable: 30,000  
 Drive Cable: 27,350  
 South cable: 25,400

Showing signs of wear.

**Problem:** \_\_\_\_\_  
**Cause:** \_\_\_\_\_  
**Remedy:** \_\_\_\_\_  
**Downtime:** \_\_\_\_\_  
**Remarks:** \_\_\_\_\_

\_\_\_\_\_  
**Completed By**                      **Completed By**                      **Completed Date**



Work Order: CENT.1271452



**Status Code:** COMP **Reported by:** AUTOGEN  
**Priority:** 8 **Date:** 22-Sep-2016  
**GL Account:** 540.210.1071.?????.00.00000.0000.10 **Phone #:**  
**Ownergroup/ Plan Area:** TM-LR **Project #:**  
**Reference:** **Parent:**  
**Location:** BSC-2210 **Gearing, Reduction and Reversing**  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 06-Oct-2016 **Target Finish:** 06-Oct-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Oct 6/16  
Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** SDUBIEL **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1271452

Operations:

Task	Description
------	-------------

10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p>
----	--

Report any of the above to trades supervisor.

note tension readings of cables including date & time

date \_\_\_\_\_

time \_\_\_\_\_

North Cable \_\_\_\_\_

Drive Cable \_\_\_\_\_

South Cable \_\_\_\_\_

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK

Completion Remarks:

13-Oct-2016

Comp

Date: October 6th, 2016

Time: 0800

North cable: 29,700

Drive cable: 29,000

South cable: 25,300

Showing signs of wear.

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

\_\_\_\_\_  
Completed By

\_\_\_\_\_  
Completed By

\_\_\_\_\_  
Completed Date





Work Order: CENT,1272428



<b>Status Code:</b>	COMP	<b>Reported by:</b>	AUTOGEN
<b>Priority:</b>	8	<b>Date:</b>	29-Sep-2016
<b>GL Account:</b>	540.210.1071.?????.00.00000.0000.10	<b>Phone #:</b>	
<b>Ownergroup/ Plan Area:</b>	TM-LR	<b>Project #:</b>	
<b>Reference:</b>		<b>Parent:</b>	
<b>Location:</b>	BSC-2210	Gearing, Reduction and Reversing	
<b>Asset:</b>			
<b>Craft:</b>	MCA	<b>Site/Vessel:</b>	BSC
<b>Shift:</b>		<b>PM:</b>	BSC-2210-PM-40
<b>Worktype:</b>			PM/INSP
<b>Target Start:</b>	13-Oct-2016	<b>Target Finish:</b>	13-Oct-2016
<b>Work Requested:</b>	Weekly Inspection of Drive & Guide Cables - Oct 13/16 Includes all three vessel cables		
<b>Job Plan:</b>	2210-BSC-SJ-40		
<b>Job Plan Desc:</b>	Cable Inspection		<b>Meter Reading:</b>
<b>Supervisor:</b>	SDUBIEL	<b>Last Reading Date:</b>	

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1272428

Operations:

Task	Description
10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p> <p>Report any of the above to trades supervisor.</p> <p>note tension readings of cables including date &amp; time</p> <p>date _____</p> <p>time _____</p> <p>North Cable _____</p> <p>Drive Cable _____</p> <p>South Cable _____</p> <p>MCA to report inspection to Lead Operator for entry into DECK LOG BOOK</p>

Completion Remarks: 15-Nov-2016

comp  
 Date: October 12, 2016  
 Time: 0800  
 North Cable: 29700  
 Drive Cable: 25900  
 South Cable: 24900

No visual damage to report

**Problem:** \_\_\_\_\_  
**Cause:** \_\_\_\_\_  
**Remedy:** \_\_\_\_\_  
**Downtime:** \_\_\_\_\_  
**Remarks:** \_\_\_\_\_

\_\_\_\_\_  
**Completed By**                      **Completed By**                      **Completed Date**



Work Order: CENT.1274931



**Status Code:** COMP **Reported by:** AUTOGEN  
**Priority:** 8 **Date:** 06-Oct-2016  
**GL Account:** 540.210.1071.?????.00.00000.0000.10 **Phone #:**  
**Ownergroup/ Plan Area:** TM-LR **Project #:**  
**Reference:** **Parent:**  
**Location:** BSC-2210 Gearing, Reduction and Reversing  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 20-Oct-2016 **Target Finish:** 20-Oct-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Oct 20/16  
 Includes all three vessel cables  
  
**No labour. Completion reporting please.**  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** SDUBIEL **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1274931

Operations:

Task	Description
------	-------------

10	<p>Inspect Drive &amp; Guide Cables.</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p>
----	---

Report any of the above to trades supervisor.

note tension readings of cables including date & time

date \_\_\_\_\_

time \_\_\_\_\_

North Cable \_\_\_\_\_

Drive Cable \_\_\_\_\_

South Cable \_\_\_\_\_

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK

Completion Remarks:

22-Nov-2016

comp

Date: October 20, 2016

Time: 8:30 am

North cable: 29,500

Drive cable: 27,600

South cable: 25,800

No defects found.

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

\_\_\_\_\_  
Completed By

\_\_\_\_\_  
Completed By

\_\_\_\_\_  
Completed Date



Work Order: CENT.1275823



**Status Code:** CLOSE **Reported by:** AUTOGEN  
**Priority:** 8 **Date:** 13-Oct-2016  
**GL Account:** 540.210.1071.?????.00.00000.0000.10 **Phone #:**  
**Ownergroup/ Plan Area:** TM-LR **Project #:**  
**Reference:** **Parent:**  
**Location:** BSC-2210 Gearing, Reduction and Reversing  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 27-Oct-2016 **Target Finish:** 27-Oct-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Oct 27/16  
Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** SDUBIEL **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1275823

Operations:

Task	Description
------	-------------

10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - Include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p>
----	--

Report any of the above to trades supervisor.

note tension readings of cables including date & time

date \_\_\_\_\_

time \_\_\_\_\_

North Cable \_\_\_\_\_

Drive Cable \_\_\_\_\_

South Cable \_\_\_\_\_

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK

---

<b>Completion Remarks:</b>	02-Nov-2016
not done - ship out of service	

---

<b>Problem:</b>	_____
<b>Cause:</b>	_____
<b>Remedy:</b>	_____
<b>Downtime:</b>	_____
<b>Remarks:</b>	_____

---

\_\_\_\_\_  
**Completed By**

\_\_\_\_\_  
**Completed By**

\_\_\_\_\_  
**Completed Date**



Work Order: CENT.1276745



**Status Code:** CLOSE **Reported by:** AUTOGEN  
**Priority:** 8 **Date:** 20-Oct-2016  
**GL Account:** 540.210.1071.?????.00.00000.0000.10 **Phone #:**  
**Ownergroup/ Plan Area:** TM-LR **Project #:**  
**Reference:** **Parent:**  
**Location:** BSC-2210 Gearing, Reduction and Reversing  
**Asset:**  
**Craft:** MCA **Site/Vessel:** BSC **Worktype:** PM/INSP  
**Shift:** **PM:** BSC-2210-PM-40  
**Target Start:** 03-Nov-2016 **Target Finish:** 03-Nov-2016  
**Work Requested:** Weekly Inspection of Drive & Guide Cables - Nov 3/16  
Includes all three vessel cables  
**Job Plan:** 2210-BSC-SJ-40  
**Job Plan Desc:** Cable Inspection **Meter Reading:**  
**Supervisor:** SDUBIEL **Last Reading Date:**

**Planned Labour:**

Task	Craft	Quantity	Hours
10	MCA	1	3.00



Work Order: CENT.1276745

Operations:

Task	Description
------	-------------

10	<p>Inspect Drive &amp; Guide Cables</p> <p>Visual inspection of the cables whilst vessel is in transit. Report any visual damage that may be seen on the cables - include estimated location of damage</p> <p>Visual damage includes: Change in color (cables are blue) Deformity Propeller nicks. Loose cable strands</p>
----	--

Report any of the above to trades supervisor.

note tension readings of cables including date & time

date \_\_\_\_\_

time \_\_\_\_\_

North Cable \_\_\_\_\_

Drive Cable \_\_\_\_\_

South Cable \_\_\_\_\_

MCA to report inspection to Lead Operator for entry into DECK LOG BOOK

Completion Remarks:

22-Nov-2016

comp - Not done. Ship out of service

Problem: \_\_\_\_\_

Cause: \_\_\_\_\_

Remedy: \_\_\_\_\_

Downtime: \_\_\_\_\_

Remarks: \_\_\_\_\_

Completed By

Completed By

Completed Date